

## Construction Office Work Orders at 2021-10-05

	Planon	PROJECT NAME	PRCD	Project Status
1	WO 0852	BRC New Autoclave and boiler combo	Davis, Thomas	6 IN CONSTRUCTION
2	WO 0972	Forestry Science- Spray booth	Davis, Thomas	6 IN CONSTRUCTION
3	WO 22012	Chemistry A205/A211 - Countertop Repair	Davis, Thomas	6 IN CONSTRUCTION
4	WO 43657	New carpet, blinds, paint for office A331	Davis, Thomas	6 IN CONSTRUCTION
5	WO 4954	Rm D428 Reno Bench, venting, cabinetry, Phase one	Davis, Thomas	6 IN CONSTRUCTION
6	WO 4957	Gas safety cabinet	Davis, Thomas	6 IN CONSTRUCTION
7	WO 42009	Office 2621	Davis, Thomas	6 IN CONSTRUCTION
8	WO 8216	FSC LAB 0320 - CFI lab renovation	Davis, Thomas	6 IN CONSTRUCTION
9	WO 48537	EAR EOSM 107 Asbestos issues	Carey, Steve	6 IN CONSTRUCTION
10	WO 5154	Coal & Min: alcove metal gate	Carey, Steve	6 IN CONSTRUCTION
11	WO 7004	P1-ICIC/X-Wing AHU-1 Cooling coil badly leaking	Carey, Steve	6 IN CONSTRUCTION
12	WO 9515	EAR Repair waterproof membrane	Carey, Steve	6 IN CONSTRUCTION
13	WO 2519	Scarfe - 1st floor- Renovate kitchen	Wenzel, Dave	6 IN CONSTRUCTION
14	WO 32742	EAR CEME-Bursting pipe Replacement	Wenzel, Dave	6 IN CONSTRUCTION
15	WO 4455	Retrofit 1 x lab bench for accessibility	Wenzel, Dave	6 IN CONSTRUCTION
16	WO 26819	NJS Reconfigure AnSo 1307 / 1309 / 1311	Wenzel, Dave	6 IN CONSTRUCTION
17	WO 4955	CHPH 142 - carpet and paint	Wenzel, Dave	6 IN CONSTRUCTION
18	WO 26806	NJS Divide AnSo 2316 into two rooms, create new door	Wenzel, Dave	6 IN CONSTRUCTION
19	WO 44051	CHPH 142 - carpet and paint	Wenzel, Dave	6 IN CONSTRUCTION
20	WO 49002	EAR Klink Pump 5 + 6 Replacement	Wenzel, Dave	6 IN CONSTRUCTION
21	WO 37542	ESB 2200 - Dean's Office Reno remove one lite	Jenn Dick	6 IN CONSTRUCTION
22	WO 2525	Buch A - Installation of Poles & Outdoor Animation Projectors	Jenn Dick	6 IN CONSTRUCTION
23	WO 11524	EAR Library is too cold	Jenn Dick	6 IN CONSTRUCTION
24	WO 29221	DSB 3131: Space renovation and acoustic consultant	Jenn Dick	6 IN CONSTRUCTION
25	WO 48434	Renovate office A327	Davis, Thomas	5 READY FOR CONSTRUCTION
26	WO 2928	EAR (UR) Pharmacy Lobby/Mezzanine lighting replacement_replaced by SR3599	Wenzel, Dave	5 READY FOR CONSTRUCTION
27	WO 4981	Office conversion from 3 to 4	Davis, Thomas	4 CONSTRUCTION ESTIMATE NEEDS APPROVAL
28	WO 6086	PS SR 238057 Planning - renovation on FSC 2322 and 2440	Davis, Thomas	4 CONSTRUCTION ESTIMATE NEEDS APPROVAL
29	WO 26999	Changing 2 single doors to 2 double doors and card access rms 092,067	Jenn Dick	4 CONSTRUCTION ESTIMATE NEEDS APPROVAL
30	WO 6912	ICICS- removal of glass wall and room divider wall	Jenn Dick	4 CONSTRUCTION ESTIMATE NEEDS APPROVAL
31	WO 33136	2716 2714 office from 2 to 3	Davis, Thomas	3 CONSTRUCTION ESTIMATION
32	WO 53581	ANSOC Refresh Rooms 2126, 2124, 2104, 2113, 1216	Davis, Thomas	3 CONSTRUCTION ESTIMATION
33	WO 47386	EAR Master SR for COVID HVAC purchasing	Carey, Steve	3 CONSTRUCTION ESTIMATION
34	WO 54610	Flag pole plaza - wire pull for pole lights	Carey, Steve	3 CONSTRUCTION ESTIMATION
35	WO 58161	Information sign damaged at Flagpole Plaza	Carey, Steve	3 CONSTRUCTION ESTIMATION
36	WO 63715	EAR ANSOC COVID Classroom Renos	Carey, Steve	3 CONSTRUCTION ESTIMATION
37	WO 63718	EAR Math COVID Classroom Renos	Carey, Steve	3 CONSTRUCTION ESTIMATION
38	WO 63726	EAR Buchanan C COVID Classroom Renos	Carey, Steve	3 CONSTRUCTION ESTIMATION
39	WO 63735	EAR Buchanan E COVID Classroom Renos	Carey, Steve	3 CONSTRUCTION ESTIMATION
40	WO 63760	EAR Math Annex COVID Classroom Renos	Carey, Steve	3 CONSTRUCTION ESTIMATION
41	WO 6981	Room 26 - Asbestos abatement	Carey, Steve	3 CONSTRUCTION ESTIMATION
42	WO 6632	Pedestrian Gate	Wenzel, Dave	3 CONSTRUCTION ESTIMATION
43	WO 6090	Refrigerated container electrical and site prep PS SR 239237	Wenzel, Dave	3 CONSTRUCTION ESTIMATION
44	WO 47324	Elevator #4-replace tile floor of cab with resilient flooring	Jenn Dick	3 CONSTRUCTION ESTIMATION
45	WO 19448	IRC 3rd Floor Replace old work stations	Jenn Dick	3 CONSTRUCTION ESTIMATION
46	WO 44809	AERL 318 Reno AV/VC	Jenn Dick	3 CONSTRUCTION ESTIMATION
47	WO 63626	Brock Hall West 105 Exterior Drain Plugged Causing a Flood in Office	Jenn Dick	3 CONSTRUCTION ESTIMATION
48	WO 6076	Chan Centre Lobby Concessions Fridges Replacement	Davis, Thomas	2 PRE DESIGN NEEDS APPROVAL
49	WO 3537	Brimacombe -- Robotics Chamber Fan and Fumehood	Davis, Thomas	1 PRE DESIGN ESTIMATE
50	WO 23058	EAR Chan wicker walls on the back screen on stage has holes in it	Carey, Steve	1 PRE DESIGN ESTIMATE
51	WO 4955	PL UNASSIGNED EAR CIRS Replace UPS	Unassigned	0 WAITING TO BE ESTIMATED
52	WO 4988	PL UNASSIGNED SR 236967 Estimate Required for the removal of UPS at MOA	Unassigned	0 WAITING TO BE ESTIMATED
53	WO 7101	UNASSIGNED EAR Humidification Boiler Relays	Unassigned	0 WAITING TO BE ESTIMATED
54	WO 13214	UNASSIGNED IKB Carpet	Unassigned	0 WAITING TO BE ESTIMATED
55	WO 13334	UNASSIGNED CF Estimate Peter Wall install fan	Unassigned	0 WAITING TO BE ESTIMATED
56	WO 15174	PL UNASSIGNED SR 230384 St. Marks College Bluephone	Unassigned	0 WAITING TO BE ESTIMATED
57	WO 17255	UNASSIGNED Conversion of locker space in MCML67C	Unassigned	0 WAITING TO BE ESTIMATED
58	WO 24789	UNASSIGNED Bio-Sciences North Wing Greenhouse - Install Two Evaporator Coolers	Unassigned	0 WAITING TO BE ESTIMATED
59	WO 26593	UNASSIGNED BRDF closing up a wall in the fuel receiving bay	Unassigned	0 WAITING TO BE ESTIMATED
60	WO 29891	UNASSIGNED Pharmacy Atrium: Impact Media Wall Renewal Project	Unassigned	0 WAITING TO BE ESTIMATED
61	WO 33663	PS UNASSIGNED Lounge lighting upgrade Previous SR226076	Unassigned	0 WAITING TO BE ESTIMATED
62	WO 40493	UNASSIGNED FSC 2621 and 2623 - Replacement of Carpet tiles	Unassigned	0 WAITING TO BE ESTIMATED
63	WO 40494	UNASSIGNED LSC 5445a - replace sink cabinet with hand-washing sink	Unassigned	0 WAITING TO BE ESTIMATED
64	WO 40679	UNASSIGNED Getting an estimate for upgrading pump condensing water supply pump	Unassigned	0 WAITING TO BE ESTIMATED
65	WO 40887	UNASSIGNED Carpet Renewal Douglas T. Kenny Building rooms: 1001, 1621, 1707 & 1709	Unassigned	0 WAITING TO BE ESTIMATED
66	WO 42432	UNASSIGNED Linoleum floor replacement MCML62	Unassigned	0 WAITING TO BE ESTIMATED
67	WO 42601	UNASSIGNED EOSM 47 - Office renovation	Unassigned	0 WAITING TO BE ESTIMATED
68	WO 43583	UNASSIGNED Brimacombe install fume hood room 343	Unassigned	0 WAITING TO BE ESTIMATED
69	WO 43770	UNASSIGNED GEOG renovate Rm 145 to include universal washroom	Unassigned	0 WAITING TO BE ESTIMATED
70	WO 48700	UNASSIGNED Chem Center D116 - Window Fan Installation with Dampers	Unassigned	0 WAITING TO BE ESTIMATED
71	WO 49429	UNASSIGNED Est done Recarpeting and repainting quotation for various offices in ANSO	Unassigned	0 WAITING TO BE ESTIMATED
72	WO 52019	UNASSIGNED Replace carpet with carpet tiles to match corridor	Unassigned	0 WAITING TO BE ESTIMATED
73	WO 53538	UNASSIGNED CEME 1050C darkroom sink remediated and new sink installed, lighting fixed	Unassigned	0 WAITING TO BE ESTIMATED
74	WO 55300	UNASSIGNED Pharm 5306/6201: conversion of lab dark rooms to equipment rooms	Unassigned	0 WAITING TO BE ESTIMATED
75	WO 58218	UNASSIGNED Frank Forward 309- NISS on 14th September	Unassigned	0 WAITING TO BE ESTIMATED
76	WO 61303	UNASSIGNED South Campus Warehouse (SCW) - RM108 Metal Shop ventilation	Unassigned	0 WAITING TO BE ESTIMATED
77	WO 61388	UNASSIGNED NJS ANSO Fume Hood Removal Estimate	Unassigned	0 WAITING TO BE ESTIMATED
78	WO 62397	UNASSIGNED Replace carpet and paint room	Unassigned	0 WAITING TO BE ESTIMATED
79	WO 65358	UNASSIGNED Geography Lab: Ponderosa Maple House	Unassigned	0 WAITING TO BE ESTIMATED